

PROGRAMMING SOFTWARE
CS-MA510TR

Thank you for choosing this Icom product. **READ ALL INSTRUCTIONS** carefully and completely before using this product.

■ **System requirements**

A PC with an OS and specifications, and the cable, listed below are required to use the CS-MA510TR.

PC

- Microsoft® Windows® 10 (32/64 bit)
- Microsoft® Windows® 8.1 (32/64 bit)*
*Except for the "RT" version.
- A USB 1.1 or 2.0 port


Cable (User supplied)

- USB cable (A - mini B type)

■ **Software installation**



When installing the software, confirm Windows has completed its startup, and then log in as the **administrator**.

1. Confirm no other applications are running.
2. Double-click "setup.exe."
 - If "User Account Control" is displayed, click <Yes> to continue.
 - If a License Agreement window is displayed, read the terms and conditions carefully. Enter a check mark and click <Install>, if you agree.
3. "Welcome to the InstallShield Wizard for CS-MA510TR" is displayed. Click <Next>>.
5. "Choose Destination Location" is displayed. Click <Next >>.
 - If desired, click <Browse...> to select another destination folder before clicking <Next >>.




4. "User Information" is displayed. Enter your name (option), your company name (option), and the product ID number as described below. Click <Next >>.
 - Product ID number: 411911-(6 digit serial number)
 - If you downloaded the software, enter the ID provided by your distributor.

Example:
When the serial number is XXXXXX*, enter "411911-XXXXXX" as the ID number.
* XXXXXX is shown as an example only, and is not valid.



6. After the installation has completed, "InstallShield Wizard Complete" is displayed. Click <Finish>.



7. A 'CS-MA510TR' group is created on the menu, and a shortcut icon is created on the desktop.

NOTE: You can uninstall the software using the "Apps & features" in the "Settings" menu. To get started, click on Start > Settings > Apps > Apps & features.

■ Before connecting the cable to the PC


To use a USB cable, you must first install a USB driver.

The latest USB driver and installation guide can be downloaded from the Icom extranet.

Read the guide carefully before installing the driver.

■ Connecting the cable

1. Hold down [⏻] for 1 second to turn OFF the transponder.
2. Connect the cable as shown below.
3. Hold down [⏻] to turn ON the transponder.



■ Reading and entering data

- To prevent data loss, read all the transponder's data before entering or editing parameters by using the software, even if the transponder is factory fresh.

Click , or <Program> in the top menu of the software, and then select "Read ← TR" to start reading.

- While reading or writing entered data, **NEVER** turn OFF the transponder or the PC, and **NEVER** disconnect the cables. Otherwise, the data could be lost or corrupted.
- Before reading or entering data, make a backup file on your PC.
A backup file enables you to easily restore if the data in the transponder is accidentally deleted.

TIP: Refer to the software's Help file for assistance with the functions or settings.
To open the Help file, click <Help> in the top menu of the software and select "Contents," or simply push the [F1] key on the PC's keyboard.

Icom, Icom Inc. and Icom logo are registered trademarks of Icom Incorporated (Japan) in Japan, the United States, the United Kingdom, Germany, France, Spain, Russia, Australia, New Zealand, and/or other countries.

Microsoft and Windows are registered trademarks of Microsoft Corporation in the United States and/or other countries.

All other products or brands are registered trademarks or trademarks of their respective holders.

Icom Inc.

1-1-32 Kamiminami, Hirano-ku, Osaka 547-0003, Japan

Count on us!

Oct. 2020

A7561-1EX
© 2020 Icom Inc.